

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401405574

Date Received:

09/16/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com
Labowskie, Steve		steve.labowskie@state.co.us
Leonard, Mike		mike.leonard@state.co.us
Inspections, All		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303694
Inspection Date: 08/23/2017 FIR Submit Date: 08/23/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 334280

Location Name: STATE GAS COM "CD"- M34N7W Number: 17NWSE County: LA PLATA
Qtrqr: NWSE Sec: 17 Twp: 34N Range: 7W Meridian: M
Latitude: 37.188182 Longitude: -107.631465

FACILITY - API Number: 05-067-00 Facility ID: 216246

Facility Name: STATE CD Number: 1
Qtrqr: NWSE Sec: 17 Twp: 34N Range: 7W Meridian: M
Latitude: 37.188182 Longitude: -107.631465

CORRECTIVE ACTIIONS:

1 CA# 94961

Corrective Action: Install or repair sign to comply with Rule 210.b. Date: 10/07/2017

Response: CA COMPLETED Date of Completion: 09/13/2017

New well head sign for both the State CD 1 and the State CD 3 has been installed at the entrance of location to

Operator Comment: comply with rule 210.b. please see attached photos

COGCC Decision: _____

COGCC Representative: _____

2 CA# 94962

Corrective Action: Install or repair sign to comply with Rule 210.d.

Date: 10/07/2017

Response: CA COMPLETED

Date of Completion: 09/13/2017

Operator Comment: Tank sign has been installed to comply with Rule 210.d.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 94963

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 09/07/2017

Response: CA COMPLETED

Date of Completion: 09/13/2017

Operator Comment: Erosion logs have been installed and staked, rock run down in the SE area has been repaired and 5 bags of musk thistle has been manually removed, bagged and disposed of on location.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: New location and tank signs have been installed on location and the storm water BMP's have been repaired and/or installed to control erosion off pad. Please see attached photos of work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 9/16/2017 8:52:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401405575 Photo documentation

Total Attach: 1 Files