

Stormwater Inspection

September 27, 2017

Operator: FIFTH CREEK ENERGY OPERATING COMPANY LLC- #10629

Location ID: 444164

Weld County, CO

SESE Section 15 T11N R63W

Chris Binschus

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Critter Creek /15
Location ID: 444164



Photo 1. Photo taken from the southeast location, facing East. Appears Operator may have installed a sediment trap but pipeline disturbance has damaged BMPs.



Photo 2. Photo taken from the southeast location, facing West. Photo illustrates pipeline construction and disturbance. Temporary BMPs (straw wattles) appear to be installed between the water line and the unconsolidated soil material.

Inspection Photos
Location Name: Critter Creek /15
Location ID: 444164



Photo 3. Photo taken from the eastern topsoil stockpile, facing West. Russian thistle has established throughout the stockpile which is not protective of topsoil per Rule 1002.c. and Russian thistle is considered weed debris which needs to be controlled per Rule 603.f.

Inspection Photos
Location Name: Critter Creek /15
Location ID: 444164



Photo 4. Photo taken from the eastern topsoil stockpile along the north-facing side, facing West. Russian thistle has established throughout the stockpile which is not protective of topsoil per Rule 1002.c. and Russian thistle is considered weed debris which needs to be controlled per Rule 603.f.

Inspection Photos
Location Name: Critter Creek /15
Location ID: 444164



Photo 5. Photo taken from the western topsoil stockpile along the south-facing side, facing East. Russian thistle has established throughout the stockpile which is not protective of topsoil per Rule 1002.c. and Russian thistle is considered weed debris which needs to be controlled per Rule 603.f.

Inspection Photos
Location Name: Critter Creek /15
Location ID: 444164



Photo 6. Photo taken from the western topsoil stockpile along the north-facing side, facing East. Russian thistle has established throughout the stockpile which is not protective of topsoil per Rule 1002.c. and Russian thistle is considered weed debris which needs to be controlled per Rule 603.f.