

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401414004

Date Received:

09/26/2017

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Abby Bazin	720-587-2356	abby.bazin@nblenergy.com
Tesla Dougherty	970-304-5245	tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684904341

Inspection Date: 09/12/2017

FIR Submit Date: 09/12/2017

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 429615

Location Name: WELLS RANCH USX Number: AA23-65-1HN County: WELD

Qtrqtr: SWS Sec: 24 Twp: 6N Range: 63W Meridian: 6

Latitude: 40.473350 Longitude: -104.393650

FACILITY - API Number: 05-123-00 Facility ID: 428363

Facility Name: WELLS RANCH AA Number: 24-65HN

Qtrqtr: SWS Sec: 24 Twp: 6N Range: 63W Meridian: 6

Latitude: 40.473350 Longitude: -104.393650

CORRECTIVE ACTIIONS:

1 CA# 99206

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/12/2017

Response: CA COMPLETED

Date of Completion: 09/25/2017

Operator Comment: The equipment was repaired and the stained soil was removed

COGCC Decision: Approved via an AMI

COGCC Representative:

2 CA# 99207

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/12/2017

Response: CA COMPLETED

Date of Completion: 09/25/2017

Operator Comment: The equipment was repaired and the stained soil was removed

COGCC Decision: Approved via an AMI

COGCC Representative:

3 CA# 99208

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/12/2017

Response: CA COMPLETED

Date of Completion: 09/25/2017

Operator Comment: Erosion was repaired and new BMPs were installed

COGCC Decision: Approved via an AMI

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Tech

Date: 9/26/2017 3:16:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401414004	FIR RESOLUTION SUBMITTED
401414016	Wells Ranch USX AA23 Response

Total Attach: 2 Files