

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2017

Submitted Date:

10/03/2017

Document Number:

674200237**FIELD INSPECTION FORM**

Loc ID _____	Inspector Name: _____ Gomez, Jason	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 1 _____ Number of Comments 0 _____ Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>5</u> Name of Operator: <u>COLORADO OIL & GAS CONSERVATION</u> Address: <u>1120 LINCOLN ST SUITE 801</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440176	NONFACILITY	AC	11/30/2014		-	Minimal Information Complaints 440176	AC

General Comment:

Inspected FacilitiesFacility ID: 440176 Type: NONFACILIT API Number: - Status: AC Insp. Status: AC**Complaint**

Comment:

Complaint #: 200443332

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 7-18--2017 Time 1100 Hrs

Contacted by Inspector:

Date: 7-18--2017-2017 Time 1130 Hrs

Well Number#: Location #: 440176

Inspection Document #: 674200237

Complainant: Eric Ewing Phone: 970-347-7737

Address: 16974 CR 40. Lasalle, CO 80645

Nature of complaint: Smoke

Field Inspector Actions:

On 7-18-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a complaint of smoke coming from a location near the residence of the complainant of Eric Ewing.

I contacted the complainant who indicated he had a seen black smoke coming from a Nobel location east of his residence. He indicated the smoke was coming from the ECD at the location.

I conducted inspection of the wells located east of the complainant's residence but I did not witness any smoke coming from any location in the area. I contacted Nobel energy and they indicated they had repaired an ECD in the area the week before the complaint.

All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date: