


Photo#1:

Overview of Location from NW corner to SE. Insert is area indicted by arrow where Stormwater settles and is flowing out of compromised berm in photo#2:



October 4, 2017

Photo#2:

SE Corner of site where Berm has been Compromised & Storm Water/Sediment is flowing Off Location



October 4, 2017

Photo#3:

View looking out from Breach from Photo #2 of Sediment Migrating Off Site.



October 4, 2017

Photo#4:

SW Corner of Pad with Access Road in Background ; BMPs need to be Installed.



October 4, 2017

Photo#5:

BMPs need to be installed along Access Road



Photo#6:



October 4, 2017

Photo#7:

Point of Access Road where Snow Melt is collecting & Culverts (indicated by arrow) need to be installed. Operator indicated that installation is scheduled.



October 4, 2017