

- Huber 2 – 34 05-067-08247



Photo 1: Wellhead sign.

- Huber 2 – 34 05-067-08247



Photo 2: Erosion channel developing off S side of pump jack.

- Huber 2 – 34 05-067-08247



Photo 3: Location overview.

- Huber 2 – 34 05-067-08247



Photo 4: Location overview.