

Inspection Photos  
Well Name: Texaco Fee 6214 Follow Up  
Location ID: 323831



**Photo 1. Follow up to inspection Doc#689400251 in response to FIRR Doc#401428410. Road has been re-graded and BMPs maintained.**