



April 7, 1955

The South Texas Development Company
715 Bank of Commerce Building
Houston 2, Texas

Gentlemen:

A representative of this Commission recently inspected the location of your abandoned J. C. Mortenson well #1, in Section 29-T9N-R56W, Colorado, and found the surface plug inadequate and leaking gas.

This situation must be corrected before the well can be considered properly plugged and abandoned.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

By A. J. Jersin, Deputy Director.

PJK H