

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/13/2017

Submitted Date:

10/13/2017

Document Number:

684904604**FIELD INSPECTION FORM**Loc ID 331149 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		pgallagh@blm.gov	BLM; federal/federal inspections
Anderson, Austin	918-845-4700	aanderson@foundationenergy.com	
Leonard, Mike		mike.leonard@state.co.us	
,		regulatory@foundationenergy.com	All Inspections
,		vkoeher@fs.fed.us	USFS; federal/federal inspections
,		dnr_cogccengineering@state.co.us	For CA Matrix inspection routing

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258928	WELL	PR	02/14/2005	OW	123-20232	FEDERAL ALBATROSS 33-12	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Stained soil at engine, around engine house, at exhaust		
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 11/13/2017
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Stained soil at wellhead, S side of pump jack		
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 11/13/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY			
Comment:	refer to locid#331150					
Corrective Action:					Date:	

Paint

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 258928 Type: WELL API Number: 123-20232 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: SI. Last produced Aug 2015. >2 years SI w/o MIT. No current MIT on record or delinquent as required by Rule 326Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 10/23/2017**BradenHead**Comment: Bradenhead not plumbed to surface.Corrective Action: Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: [refer to locid#331150](#)

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401429558	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4274298
684904605	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4274295