

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401436535

Date Received:

10/20/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Tesla Dougherty	970-304-5245	tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682502615

Inspection Date: 09/28/2017

FIR Submit Date: 09/29/2017

FIR Status:

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 405904

Location Name: RITCHEY H-63N65W Number: 27SWSW County:

Qtrqr: SWS Sec: 27 Twp: 3N Range: 65W Meridian: 6
W

Latitude: 40.190930 Longitude: -104.656890

FACILITY - API Number: 05-123-00 Facility ID: 405904

Facility Name: RITCHEY H-63N65W Number: 27SWSW

Qtrqr: SWS Sec: 27 Twp: 3N Range: 65W Meridian: 6
W

Latitude: 40.190930 Longitude: -104.656890

CORRECTIVE ACTIONS:

1 CA# 103278

Corrective Action: Remove riser at battery location in accordance to reclamation rule 1004.a

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 05/17/2017

Operator Comment: Riser was removed in May of 2017. Landowner reclaimed and seeded.

COGCC Decision: Not Approved

COGCC Representative: Operator states "riser was removed in May of 2017". Initial inspection requiring riser removal was June 2017. Two additional inspections have been performed on August, 2017 and September, 2017 documenting that riser remains at the battery location. Corrective action requiring removal of the riser in accordance to 1004.a remains applicable, location will remain out of compliance until corrective action has been addressed.

Operator states "Landowner reclaimed and seeded". Operator remains responsible for the reclamation of the location(s) and access road in accordance to COGCC's 1000 series reclamation rules and standards, regardless of who performs the work; A follow-up inspection will be performed to determine if work has been conducted in accordance to COGCC reclamation rules and standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Tech

Date: 10/20/2017 1:39:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401436535	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files