

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Brigade 7		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Survey Line around location.		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 421616 Type: WELL API Number: 123-32978 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): 2 Sacks

Good Return During Job: YES

Cement Type: _____

Comment: Reliance Wire line setting cast iron bridge plug at 3911 ft. at time of inspection.

Corrective Action:

Date: _____

Workover

Comment: Brigade 7

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
Routine PA inspection. Well had been serviced with a hydraulic lift syste.	carlilec	10/26/2017