

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2017

Submitted Date:

11/10/2017

Document Number:

682600389**FIELD INSPECTION FORM**
 Loc ID 309600 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10581Name of Operator: ABILENE PERFECT ENERGY JV LLCAddress: 4600 PECOS STREETCity: DENVER State: CO Zip: 80211**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
McGregor, Al	(303) 520-4438	almc@perfectenergy.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218179	WELL	PR	05/20/2013	OW	073-06164	1-6 S-S-M MELLOTT 1	EI

General Comment:

This inspection is a follow up to COGCC Complaint 200444490. Heater treater on well head was reported to be leaking by complainant and cattle were drinking produced water leaking from tank. Operator was informed of leak and downed fences on well pad.

Current inspection indicates that fencing near the cattle guard on the north side of the location has been fixed. Gate on the south side of the location was down during this inspection and previous inspection. Gate is in disrepair and it was not possible to close. Operator shall fix gate to prevent access to well pad by cattle.

Heater treater is still actively leaking produced water. Leak is a pinhole leak and at this time does not appear to be a reportable leak. Operator shall immediately stop leak. This may require draining tank to properly fix leak.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 1

Comment: Heater treater on location is leaking through a small hole in the tank. Leak reported on 10/24/2017 via landowner complaint to COGCC. Control and contain spills/releases and clean up per Rule 906.a.

Corrective Action: Operator shall immediately stop leak.

Date: 11/11/2017

Reportable: NO

GPS: Lat _____ Long _____

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
At this time COGCC Complaint 200444490 remains open until operator address issues with leak and fencing of well pad.	kosolaj	11/10/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600390	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4299106