

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2017

Submitted Date:

11/15/2017

Document Number:

684904705**FIELD INSPECTION FORM**
 Loc ID 440718 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10359Name of Operator: WARD PETROLEUM CORPORATIONAddress: 215 WEST OAK STREET #1000City: FORT COLLINS State: CO Zip: 80521**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		jeffd@wardpetroleum.com	
Hal, Marshall	970-3895487	marshall@wardpetroleum.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445283	TANK BATTERY	AC	04/11/2014		-	Schaefer 24-3-7HC	AC

General Comment:

Inspected FacilitiesFacility ID: 445283 Type: TANK API Number: - Status: AC Insp. Status: AC**Complaint**Comment: [Complaint #: 200444609, 200444610](#)[Field Inspector Assigned: C Pesicka](#)[Well Number: 05- Location #: 440718](#)[Inspection Document #: 684904705](#)[Nature of complaint: Sound](#)[If Sound GPS Coordinates of Survey Location: n/a](#)[Inspection Observations:](#)[Site was in upset condition prior, see doc#684904679. Spoke with complainant who has stated that the vibration has not occurred since the upset condition was brought under control. Ward has changed the VRUs to handle a different pressure load.](#)[18A doc#: 200444659, 200444661](#)

Corrective Action:

Date: