

DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:
401466561

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10110 Contact Name: Michael Andrews
 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC Phone: (970) 433-8704
 Address: 1801 BROADWAY #500 Fax: _____
 City: DENVER State: CO Zip: 80202 Email: mandrews@gwogco.com

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____

API Number 05-123-07399-00
 Well Name: KENNETH THAYER Well Number: 1
 Location: QtrQtr: SWSW Section: 30 Township: 6N Range: 67W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WILDCAT Field Number: 99999

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.452183 Longitude: -104.941667
 GPS Data:
 Date of Measurement: 07/13/2017 PDOP Reading: 1.2 GPS Instrument Operator's Name: James Freshwater
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	7755	7768	08/30/1972	B PLUG CEMENT TOP	7350
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	28	211	155	211	0	VISU
1ST	7+7/8	4+1/2	11.6	7,876	200	7,876	6,477	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	200	sks cmt from	2400	ft. to	1719	ft.	Plug Type: <u>OPEN HOLE</u>	Plug Tagged: <input type="checkbox"/>
Set	418	sks cmt from	1250	ft. to	105	ft.	Plug Type: <u>OPEN HOLE</u>	Plug Tagged: <input type="checkbox"/>
Set	32	sks cmt from	211	ft. to	105	ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set	35	sks cmt from	105	ft. to	0	ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: 10/28/2017
 *Wireline Contractor: N/A *Cementing Contractor: O-Tex
 Type of Cement and Additives Used: Class G
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Job Summary:
 Drill cmt plug and washed to 2485'.
 Pumped 200sx cmt from 2400' to 1719'
 Pumped 450sx cmt from 1250' to Surface
 Topped off from 105' to surface with 35sx cmt.
 Cut and cap

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Michael Andrews
 Title: Operations Engineer Date: _____ Email: mandrews@gwogco.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

<u>COA Type</u>	<u>Description</u>

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401466744	WELLBORE DIAGRAM
401466745	CEMENT JOB SUMMARY

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)