

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401471263
Date Received:
11/29/2017

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Tesla Dougherty	970-304-5245	denise.arthur@state.co.us tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 675103826
Inspection Date: 08/14/2017 FIR Submit Date: 08/15/2017 FIR Status:

Inspected Operator Information:

Company Name: NOBLE ENERGY INC Company Number: 100322
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 328029

Location Name: MOSER H Number: 34-30D County:
Qtrqr: NWN Sec: 34 Twp: 3N Range: 65W Meridian: 6
W
Latitude: 40.187190 Longitude: -104.656770

FACILITY - API Number: 05-123-00 Facility ID: 328029

Facility Name: MOSER H Number: 34-30D
Qtrqr: NWN Sec: 34 Twp: 3N Range: 65W Meridian: 6
W
Latitude: 40.187190 Longitude: -104.656770

CORRECTIVE ACTIIONS:

1 CA# 92448

Corrective Action: Perform reclamation in accordance to COGCC 1000 series reclamation requirements including, but not limited, compaction alleviation. Date: 09/15/2017

Response: CA COMPLETED Date of Completion: 11/08/2017

Operator Comment: The landowner planted a new alfalfa crop, we'll assess growth in the spring, and if stunted, we'll address compaction issues in the Fall of 2018.

COGCC Decision: **Not Approved**

COGCC Representative: Inspection #682502119 dated 6/1/2017 provided operator opportunity to collaborate with the surface owner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities, and to provide a schedule by 6/16/2017. Operator failed to respond to this inspection or submit a form 4.

Follow-up Inspection #675103826 dated 8/14/2017 documented that the crop within the field had been harvested, and the field was currently bare. Operator was then given a corrective action date of 9/15/2017 to perform the required reclamation.

Not approving resolution of corrective action complete. Operator statements indicate no work has been performed per the corrective action. Location will remain out of compliance until corrective action has been addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 11/29/2017 2:45:06 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401471263	FIR RESOLUTION SUBMITTED
401471265	Moser 34-4

Total Attach: 2 Files