

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401471269

Date Received:

11/29/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Tesla Dougherty

Phone

970-304-5245

Email

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 675103823

Inspection Date: 08/14/2017

FIR Submit Date: 08/15/2017

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 328030

Location Name: MOSER-63N65W Number: 34SWNW County: _____

Qtrqr: SWN Sec: 34 Twp: 3N Range: 65W Meridian: 6
W

Latitude: 40.183660 Longitude: -104.656790

FACILITY - API Number: 05-123- -00 Facility ID: 328030

Facility Name: MOSER-63N65W Number: 34SWNW

Qtrqr: SWN Sec: 34 Twp: 3N Range: 65W Meridian: 6
W

Latitude: 40.183660 Longitude: -104.656790

CORRECTIVE ACTIONS:

1 CA# 92446

Corrective Action: Perform reclamation in accordance to COGCC 1000 series reclamation requirements including, but not limited, compaction alleviation.

Date: 09/15/2017

Response: CA COMPLETED

Date of Completion: 11/08/2017

Operator Comment: The landowner planted a new alfalfa crop, we'll assess growth in the spring, and if stunted, we'll address compaction issues in the Fall of 2018.

COGCC Decision: **Not Approved**

COGCC
Representative:

Inspection #682502122 dated 6/1/2017 provided operator opportunity to collaborate with the surface owner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities, and to provide a schedule by 6/16/2017. Operator failed to respond to this inspection or submit a form 4.

Follow-up Inspection #675103823 dated 8/14/2017 documented that the crop within the field had been harvested, and the field was currently bare. Operator was then given a corrective action date of 9/15/2017 to perform the required reclamation.

Not approving resolution of corrective action complete. Operator statements indicate no work has been performed per the corrective action. Location will remain out of compliance until corrective action has been addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 11/29/2017 2:47:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|--------------------------|
| 401471269 | FIR RESOLUTION SUBMITTED |
| 401471277 | Moser H34-5 |

Total Attach: 2 Files