

Photo#1:

Area at South end of Pad where Chanel erosion is occurring.



November 24, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana N Parachute Loc#335622

Photo#2:

View of eroding area from South to North.



November 24, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana N Parachute Loc#335622

Photo#3:

Well recontoured & vegetated Cut Slope at East side of Location



November 24, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana N Parachute Loc#335622

Photo#4:

Second Retention Pond at base of South Fill Slope



November 24, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana N Parachute Loc#335622