

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401483879

Date Received:
12/12/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Lindsey Rider

970-285-2711

lrider@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102427

Inspection Date: 11/24/2017

FIR Submit Date: 11/27/2017

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335676

Location Name: NPR Number: K10-596 County: _____

Qtrqtr: NESW Sec: 10 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.627280 Longitude: -108.155610

FACILITY - API Number: 05-045-00 Facility ID: 335676

Facility Name: NPR Number: K10-596

Qtrqtr: NESW Sec: 10 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.627280 Longitude: -108.155610

CORRECTIVE ACTIONS:

1 CA# 112074

Corrective Action: Clean up stained Soil around Well Heads.

Date: 12/04/2017

Response: CA COMPLETED

Date of Completion: 12/04/2017

Operator Comment: Stained soil removed from location.

COGCC Decision: _____

COGCC
Representative:

2 CA# 112075

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details; performing further enlargement/definition of ditch if determined necessary to make it an effective BMP.

Date: 12/01/2017

Response: CA COMPLETED

Date of Completion: 12/04/2017

Operator
Comment: Stormwater controls repaired.

COGCC Decision: _____

COGCC
Representative:

3 CA# 112076

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 12/01/2017

Response: CA COMPLETED

Date of Completion: 12/04/2017

Operator
Comment: Stormwater controls repaired.

COGCC Decision: _____

COGCC
Representative:

4 CA# 112077

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 12/01/2017

Response: CA COMPLETED

Date of Completion: 12/04/2017

Operator
Comment: Stormwater controls repaired.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: _____

Title: EHS Lead

Date: 12/12/2017 3:19:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files