

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401485160
Date Received:
12/13/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>Sabre.Beebe@bp.com</u>
<u>-</u>		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602251
Inspection Date: 11/08/2017 FIR Submit Date: 11/28/2017 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326059

Location Name: MAGOON FEDERAL GU B-N35N6W Number: 19SESE County: LA PLATA
Qtrqr: SESE Sec: 19 Twp: 35N Range: 6W Meridian: N
Latitude: 37.282628 Longitude: -107.564863

FACILITY - API Number: 05-067-00 Facility ID: 215795

Facility Name: MAGOON FEDERAL B Number: 1
Qtrqr: SESE Sec: 19 Twp: 35N Range: 6W Meridian: N
Latitude: 37.282628 Longitude: -107.564863

CORRECTIVE ACTIIONS:

1 CA# 112161

Corrective Action: Stormwater controls are needed to stabilize concentrated runoff and stormwater run-on in the project area. These should be installed no later than December 30, 2017. Original corrective action date will remain to document time since original corrective action. Date: 05/01/2017

Response: CA COMPLETED Date of Completion: 12/12/2017

BP has addressed the storm water issues on this location by re-establishing diversion ditches and installing rock run downs. Please see attached photos.

Operator _____
Comment: _____

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: BP has addressed the storm water issues on this location by re-establishing diversion ditches and installing rock run downs. Please see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: _____

Title: Construction Specialist Date: 12/13/2017 2:07:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401485179	Storm water BMP photos

Total Attach: 1 Files