

JAN 26 1996

COLORADO



99999999

# VATION COMMISSION REPORT

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

- ☒ NOTICE OF UNSATISFACTORY INSPECTION  
☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05- 075-5711

LEASE NAME: State

LOCATION: SENECA 22-8N-54

OPERATOR: Pease

DATE: 1-11-96

INSPECTOR: Brinton

Insp. Type: SR

Insp. Status: PA

PA: Y

N

Pass/Fail: P

F

Viol.: Y

N

NOV: Y

N

## INSPECTION ITEM

## COMMENTS

## INPUT

Well ID Signs (Rule 210)	None	
Pits (Reserve/Production) (Rule 902, 903, 904)	pit 200 <sup>2</sup>	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	2-300, VHT, Sy, GM	
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	tubing pulled, casing top open - possibly plugged.	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)	pump disconnected	
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	gravel pit / work pit open	
Miscellaneous		



00248014

CORRECTIVE ACTION REQUIRED: Comply with Rule 317b.  
this well was well in July of 1995 (SR)

Date Corrective Action Required By: 2-15-96 Date Remedied: 1-24-96

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site