

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401493444

Date Received:

12/21/2017

FIR RESOLUTION FORM

CA Summary:

20 of 27 CAs from the FIR responded to on this Form

20 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Alyssa Beard

3032448114

abeard@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 681700954

Inspection Date: 11/28/2017

FIR Submit Date: 12/04/2017

FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 331795

Location Name: WICKSTROM-67N59W Number: 6SWNW County: WELD

Qtrqr: SWN Sec: 6 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.607920 Longitude: -104.026164

FACILITY - API Number: 05-123-00 Facility ID: 266038

Facility Name: WICKSTROM Number: 6-5

Qtrqr: SWN Sec: 6 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.607920 Longitude: -104.026164

CORRECTIVE ACTIONS:

1 CA# 112822

Corrective Action: Install berms or other secondary containment devices per Rule 605.a.(4) (skim tank).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/14/2017

Operator
Comment: photo 0386

COGCC Decision: **Not Approved**

COGCC Representative: Operator comment and photo do not demonstrate compliance with CA.

2 ☒ CA# 112823

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4) (crude oil ASTs).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator Comment: Photo 0385

COGCC Decision: Approved via an AMI

COGCC Representative:

3 ☒ CA# 112824

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d (skim tank).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator Comment: Photo 0386

COGCC Decision: Approved via an AMI

COGCC Representative:

4 ☒ CA# 112825

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d (300 bbl crude oil ASTs)

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator Comment: Photo 0384,0385

COGCC Decision: Approved pending re-inspection

COGCC Representative: Operator comment and photo do not demonstrate compliance with CA.

5 ☒ CA# 112826

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d (400 bbl crude oil ASTs).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator Comment: Photo 0382

COGCC Decision: Approved pending re-inspection

COGCC Representative: Operator comment and photo do not demonstrate compliance with CA.

6 ☒ CA# 112827

Corrective Action: Immediately remove and properly dispose of oily waste beneath production tank loadline, per Rule 907.e

Date: 08/29/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator
Comment: 0384

COGCC Decision: Approved via an AMI

COGCC
Representative:

7 ☒ CA# 112828

Corrective Action: Remove and properly dispose of oily waste beneath flowline riser east of crude oil ASTs, per Rule 907.e.

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator
Comment: Photo 0385

COGCC Decision: **Not Approved**

COGCC
Representative: '400 bbl tanks' and 'berms' photos do not adequately demonstrate CA compliance.

8 ☒ CA# 112829

Corrective Action: Remove and properly dispose of oily waste associated with wellhead, per Rule 907.e.

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator
Comment: Photo 0387

COGCC Decision: Approved via an AMI

COGCC
Representative:

9 ☒ CA# 112830

Corrective Action: Remove and properly dispose of oily waste beneath tank valves, per Rule 907.e.

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 12/13/2017

Operator
Comment: Photo attached

COGCC Decision: Approved via an AMI

COGCC
Representative:

11 ☒ CA# 112832

Corrective Action: Remove and properly dispose of oily waste at skim tank outlet, per Rule 907.e.

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

0386

Operator
Comment:

COGCC Decision: Approved via an AMI

COGCC
Representative:

12  CA# 112833

Corrective Action: Remove and properly dispose of oily waste inside of Wickstrom #6-5 treater shed, per Rule 907.e.

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator
Comment: Photo attached

COGCC Decision: **Not Approved**

COGCC
Representative: Attached photos correspond to Wickstrom #6-4 treater shed.

14  CA# 112835

Corrective Action: Comply with Rule 603.f (55-gallon drum).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator
Comment: Drum removed, photo 0385

COGCC Decision: Approved via an AMI

COGCC
Representative:

15  CA# 112836

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d (flowlines).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator
Comment: 0380, 0381

COGCC Decision: Approved pending re-inspection

COGCC
Representative: '400 bbl tanks' photo shows oily waste underlying flowline SE of 400 bbl ASTs.

16  CA# 112837

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d (vertical heater treater).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator
Comment: 0380

COGCC Decision: Approved via an AMI

COGCC
Representative:

18 ☒ CA# 112839

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1) (day tank).

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator
Comment: 55-gallon drum removed from premises photo 0392

COGCC Decision: Approved via an AMI

COGCC
Representative:

21 ☒ CA# 112842

Corrective Action: Comply with Rule 603.f (horizontal heater treater and pump jack).

Date: 01/26/2018

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator
Comment: Photo 0389, 0392

COGCC Decision: **Not Approved**

COGCC
Representative:

Operator photos do not demonstrate compliance with Rule 603.f for unused equipment.

23 ☒ CA# 112844

Corrective Action: Comply with Rule 603.f (debris).

Date: 11/05/2017

Response: CA COMPLETED

Date of Completion: 12/13/2017

Operator
Comment: Photo 0392

COGCC Decision: Approved via an AMI

COGCC
Representative:

25 ☒ CA# 112846

Corrective Action: Remit records of work performed under Remediation Project #1834 or contact EPS Steven Arauza to discuss closure requirements.

Date: 12/15/2017

Response: CA COMPLETED

Date of Completion: 11/16/2017

Operator
Comment: Alyssa Beard contacted Steven Arauza to discuss closure.

COGCC Decision: Approved via an AMI

COGCC
Representative:

26 ☒ CA# 112847

Corrective Action: Immediately repair wildlife protection equipment, per Rule 902.d.

Date: 09/03/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator
Comment: Photo 0386COGCC Decision: **Not Approved**COGCC
Representative: 'Skim tank' photo does not adequately demonstrate CA compliance.27  CA# 112848

Corrective Action: Remove and properly dispose of oily waste, per Rule 907.e (production pit).

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator
Comment: Photo 0378COGCC Decision: **Not Approved**COGCC
Representative: 'Skim tank' photo does not adequately demonstrate CA compliance.OPERATOR COMMENT AND SUBMITTAL

Comment: Signs will be installed once they have arrived.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: EHS Specialist

Date: 12/21/2017 3:58:46 PM

ATTACHMENT LISTView Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401493444	FIR RESOLUTION SUBMITTED
401493447	Berms
401493452	Tank
401493455	Tank LOs
401493461	400 bbl tanks
401493824	pump jack overview
401493833	Horizontal
401494074	Shed floor
401494077	Shed floor
401494197	pump jack overview

Total Attach: 10 Files