

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401500703

Date Received:
01/03/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Fischer, Alex

alex.fischer@state.co.us

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674901989

Inspection Date: 12/01/2017

FIR Submit Date: 12/04/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306936

Location Name: MERRY FEDERAL G. U.-M34N6W Number: 10NWNE County: LA PLATA

Qtrqtr: NWNE Sec: 10 Twp: 34N Range: 6W Meridian: N

Latitude: 37.232586 Longitude: -107.511393

FACILITY - API Number: 05-067- -00 Facility ID: 280384

Facility Name: MERRY FEDERAL Number: 2

Qtrqtr: NWNE Sec: 10 Twp: 34N Range: 6W Meridian: N

Latitude: 37.232586 Longitude: -107.511393

CORRECTIVE ACTIONS:

1 CA# 112925

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS.

Date: 01/04/2018

Response: CA COMPLETED

Date of Completion: 12/11/2017

For the packing leak: "BP has replaced the stuffing box packing, aligned the polished rod of the beam pump, and installed an automatic packing leak detection shutoff device - See attached Photo"

Operator Comment: We are currently awaiting lab results to determine if any remedial action is necessary. At this time, remediation is unknown, but will likely be either no action or a gypsum amendment to the impacted area.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: For the packing leak: "BP has replaced the stuffing box packing, aligned the polished rod of the beam pump, and installed an automatic packing leak detection shutoff device - See attached Photo
We are currently awaiting lab results to determine if any remedial action is necessary. At this time, remediation is unknown, but will likely be either no action or a gypsum amendment to the impacted area.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Construction Specialist

Date: 1/3/2018 8:58:24 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

401500710	Equipment installation photo
-----------	------------------------------

Total Attach: 1 Files