

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2018

Submitted Date:

01/04/2018

Document Number:

674200407**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Gomez, Jason 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440176	NONFACILITY	AC	11/30/2014		-	Minimal Information Complaints 440176	UN

General Comment:

Inspected FacilitiesFacility ID: 440176 Type: NONFACILIT API Number: - Status: AC Insp. Status: UN**Complaint**

Comment:

Well Number#:
Location #: 440176
Inspection Document #: 674200407
Complaint #

Nature of complaint: Noise

Field Inspector Actions:

On 1-4-2018, I was contacted by complaint specialist Megan Adamczyk in reference to a noise complaint received for 1-4-2018 by the COGCC about possible oil and gas noise occurring in the Windsor area somewhere around the complaints residence.

On 1-4-2018 I contacted the complaint who indicated he was experiencing a noise which he associated with reverberation coming from one of the wells in areas equipment. The complaint indicated the noise was very intermittent.

On 1-4-2018 at approx. 1100 Hrs I performed inspections of the oil and gas operations in the area. At the time of the inspections I did not find any abnormal operation in the area which could be contributing to the noise experienced by the complaint. I contacted both Bayswater and PDC and advised them of the complaint and asked them to monitor their equipment. Due to the intermittent noise and not finding any noise source in the area no noise study was performed.

All information reviewed and site inspection information were submitted to the COGCC for further review.

No violations of COGCC rules were observed at the time of this inspection

Corrective Action:

Date: