

- Bush Federal 2
- 05-067-08663



**Photo 1: Impacted soil and gravel. Previous inspection.**

- Bush Federal 2
- 05-067-08663



**Photo 2: Cleaned up impacted soil.**

- Bush Federal 2
- 05-067-08663



**Photo 3: Treated logs dumped on location. Previous inspection.**

- Bush Federal 2
- 05-067-08663



**Photo 4: Treated logs moved off location into tree line.**

- Bush Federal 2
- 05-067-08663



**Photo 5: Chunks of concrete (1 of 4). Previous inspection.**

- Bush Federal 2
- 05-067-08663



**Photo 6: Cleaned up concrete chunks.**

- Bush Federal 2
- 05-067-08663



**Photo 7: Wire rope. Previous inspection.**

- Bush Federal 2
- 05-067-08663



**Photo 8: Removed wire rope.**

- Bush Federal 2
- 05-067-08663



**Photo 9: Erosion channels. Previous inspection.**

- Bush Federal 2
- 05-067-08663



**Photo 10: Repaired erosion channels.**

- Bush Federal 2
- 05-067-08663



**Photo 11: Erosion channel with dumped logs in background. Previous inspection.**

- Bush Federal 2
- 05-067-08663



**Photo 12: Repaired erosion channel with stacked logs in background.**

- Bush Federal 2
- 05-067-08663



Photo 13: Wellhead sign.

- Bush Federal 2
- 05-067-08663



Photo 14: Location overview with new berm.