

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2018

Submitted Date:

01/16/2018

Document Number:

677400356**FIELD INSPECTION FORM**Loc ID 320071 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: **Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Findings:**10 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202495	WELL	PR	08/20/2008	GW	001-07900	CHAMPLIN 485 AMOCO 1	SI

General Comment:

Location**Lease Road:**

Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	ok	
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
Crude Oil	Tank	>= 5 bbls		
Comment:	soiled dirt in front of tank by valves			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 02/16/2018

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		39.557150,-104.090590	
Comment:	capacity on water tank 210 bbls Berms wil not hold cacity of water tank					
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.					Date: 01/31/2018

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	berms will not hold capacity of water tank			
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.			Date: 01/31/2018

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		39.556970,-104.090450
Comment:	need cap on load line				
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.				Date: 01/21/2018

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	berms will not hold capacity of water tank			
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.			Date: 01/31/2018

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 202495 Type: WELL API Number: 001-07900 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**BradenHead**Comment: Corrective Action: Date: _____**COGCC Comments**

Comment	User	Date
document # 671101676 dated 7/1/14 only well sign has been installed	montoyaj	01/16/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677400357	well sign and battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352718
677400358	stained soil at load lines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352719
677400359	berms on water tank and cap on load line	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352720