

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401520975

Date Received:

01/22/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902012  
Inspection Date: 01/03/2018 FIR Submit Date: 01/03/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333970

Location Name: BLACK GAS UNIT 21-22-M34N8W Number: 22SENE County: LA PLATA  
Qtrqtr: SENE Sec: 22 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.179521 Longitude: -107.699574

FACILITY - API Number: 05-067-00 Facility ID: 297200

Facility Name: BLACK 21-22 Number: 4  
Qtrqtr: SENE Sec: 22 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.179521 Longitude: -107.699574

CORRECTIVE ACTIONS:

1 CA# 113702

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS. Date: 02/05/2018

Response: CA COMPLETED Date of Completion: 01/16/2018

Stained soils around the well head and the exhaust were removed on 1/16/18. The soil pile on the edge of pad was utilized to back fill the clean up areas. A metal base has been connected to the exhaust to catch any

Operator Comment: particulates that may stain the soils in the future. All stained soils were disposed of in the BP soil box at the Operations Center for remediation in bulk at IEI in Farmington NM. See attached photos of clean up completion.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

2 CA# 113703

Corrective Action: Comply with Rule 603.f.

Date: 04/03/2018

Response: CA COMPLETED

Date of Completion: 01/12/2018

Operator Comment: Soil pile stored on location was utilized to back fill areas where stained soils were located to prevent the safety hazard of uneven ground in these areas see attached photos.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective actions on this location have been addressed see attached photos of work completed on location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: \_\_\_\_\_

Title: Compliance Specialist Date: 1/22/2018 11:45:27 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401521588	Work completion photos

Total Attach: 1 Files