

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401533860
Date Received:
02/02/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96705
Name of Operator: WPX ENERGY PRODUCTION LLC
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Deborah Watson	505-333-1880	deborah.watson@wpxenergy.com
Lacey Granillo	505-333-1816	lacey.granillo@wpxenergy.com
Darren Rowley	505-947-4974	drowley@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602456
Inspection Date: 01/17/2018 FIR Submit Date: 01/26/2018 FIR Status:

Inspected Operator Information:

Company Name: WPX ENERGY PRODUCTION LLC Company Number: 96705
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

LOCATION - Location ID: 385880

Location Name: BONDAD 33-9-N33N9W Number: 29NWSW County: LA PLATA
Qtrqr: NWS Sec: 29 Twp: 33N Range: 9W Meridian: N
Latitude: 37.072509 Longitude: -107.852877

FACILITY - API Number: 05-067-00 Facility ID: 216483

Facility Name: BONDAD 33-9 Number: 52
Qtrqr: NWS Sec: 29 Twp: 33N Range: 9W Meridian: N
Latitude: 37.072509 Longitude: -107.852877

CORRECTIVE ACTIONS:

1 CA# 114204

Corrective Action: Reclaim project area to 1004 reclamation rules within the spring seeding window and no later than May 1, 2018.

Date: 05/01/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator
Comment:

sent via FIRR

February 1, 2018

State of Colorado - Oil and Gas Conservation Commission
Attn: Catherine Roy
1120 Lincoln Street, Suite 801
Denver, CO 80203

RE: Field Inspection Form No. 680602456 pertaining to Bondad 33-9 #52

Ms. Roy,

This Letter is intended to respond to the corrective action suggested in Field Inspection Form No. 680602456 pertaining to the Bondad 33-9 #52 well (API 05-067-08089, Location ID 385880). This well was recently sold by WPX Energy Production, LLC, to LOGOS Resources II, LLC, and is presently operated by LOGOS Operating, LLC ("LOGOS"), pending approval of submitted Changes of Operator.

A review of the Colorado Oil and Gas Conservation Commission ("COGCC") website reflects the attached Sundry Notice submitted July 20, 2006, and approved by the COGCC September 19, 2006. The sundry states the following:

"The landowner, Jeff Paxton, was consulted on 7/18/06 concerning rehabilitation of the location and he said he did not want any rehab done. Attached to this Sundry is a statement signed by Mr. Paxton."

In reliance upon the approved Sundry discussed above, LOGOS believes that the Bondad 33-9 #52 well site has been reclaimed in compliance with COGCC regulations and respectfully requests reevaluation of Field Inspection Form No. 680602456 in a manner consistent with the attached sundry.

If any further information is necessary, please contact me at 505-947-4974. Thank you.

Sincerely,
LOGOS Operating, LLC

Darren Rowley
Title: Ignacio Production Lead & Stakeholder Engagement

Please see attached letter and 2006 sundry.

COGCC Decision: **Not Approved**

COGCC
Representative:

See supervisor comment.

COGCC
Supervisor:

COGCC database indicates that WPX is the operator of record and is therefore the responsible party. No Form 10 on file for this location/well.

Site has significant erosion control issues, and a variance for stormwater is not possible.

Location does not meet the required burden for a variance. Reclaim the location per the corrective action date. Location remains out of compliance until reclamation is completed.

The Form 4-Sundry notice referred to in the operator comment and in the database is a notification of abandoned location and does not pass final reclamation. A passing final reclamation inspection is required.

2  CA# 114205

Corrective Action:

Reclaim project area. Stormwater erosion needs to be monitored and controlled throughout reclamation until the location achieves long term stabilization.

Date: 05/01/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator
Comment:

sent via FIRR

February 1, 2018

State of Colorado - Oil and Gas Conservation Commission
Attn: Catherine Roy
1120 Lincoln Street, Suite 801
Denver, CO 80203

RE: Field Inspection Form No. 680602456 pertaining to Bondad 33-9 #52

Ms. Roy,

This Letter is intended to respond to the corrective action suggested in Field Inspection Form No. 680602456 pertaining to the Bondad 33-9 #52 well (API 05-067-08089, Location ID 385880). This well was recently sold by WPX Energy Production, LLC, to LOGOS Resources II, LLC, and is presently operated by LOGOS Operating, LLC ("LOGOS"), pending approval of submitted Changes of Operator.

A review of the Colorado Oil and Gas Conservation Commission ("COGCC") website reflects the attached Sundry Notice submitted July 20, 2006, and approved by the COGCC September 19, 2006. The sundry states the following:

"The landowner, Jeff Paxton, was consulted on 7/18/06 concerning rehabilitation of the location and he said he did not want any rehab done. Attached to this Sundry is a statement signed by Mr. Paxton."

In reliance upon the approved Sundry discussed above, LOGOS believes that the Bondad 33-9 #52 well site has been reclaimed in compliance with COGCC regulations and respectfully requests reevaluation of Field Inspection Form No. 680602456 in a manner consistent with the attached sundry.

If any further information is necessary, please contact me at 505-947-4974. Thank you.

Sincerely,
LOGOS Operating, LLC

By: Darren Rowley
Title: Ignacio Production Lead & Stakeholder Engagement

Please see attached letter and 2006 sundry.

COGCC Decision: **Not Approved**

COGCC
Representative: See Supervisor comment.

COGCC
Supervisor: COGCC database indicates that WPX is the operator of record and is therefore the responsible party. No Form 10 on file for this location/well.

Site has significant erosion control issues, and a variance for stormwater is not possible.

Location does not meet the required burden for a variance. Reclaim the location per the corrective action date. Location remains out of compliance until reclamation is completed.

The Form 4-Sundry notice referred to in the operator comment and in the database is a notification of abandoned location and does not pass final reclamation. A passing final reclamation inspection is required.

OPERATOR COMMENT AND SUBMITTAL

Comment: This well was recently sold by WPX Energy Production, LLC, to LOGOS Resources II, LLC, and is presently operated by LOGOS Operating, LLC ("LOGOS"), pending approval of submitted Changes of Operator.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deborah Watson

Signed: _____

Title: Environmental Specialist

Date: 2/2/2018 7:55:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401533860	FIR RESOLUTION SUBMITTED
401533878	2006 Sundry Notice
401533882	Logos Response to Doc No. 680602456

Total Attach: 3 Files