

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401534346
Date Received:
02/02/2018

FIR RESOLUTION FORM

CA Summary:
2 of 3 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Brian Dodek 7204406100 BDodek@Bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403207
Inspection Date: 01/12/2018 FIR Submit Date: 01/19/2018 FIR Status:

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 438730

Location Name: State Pronghorn Number: V-32 Pad County:
Qtrqtr: NENE Sec: 32 Twp: 5N Range: 61W Meridian: 6
Latitude: 40.361060 Longitude: -104.225190

FACILITY - API Number: 05-123-00 Facility ID: 438730

Facility Name: State Pronghorn Number: V-32 Pad
Qtrqtr: NENE Sec: 32 Twp: 5N Range: 61W Meridian: 6
Latitude: 40.361060 Longitude: -104.225190

CORRECTIVE ACTIIONS:

1 CA# 114139

Corrective Action: Comply with Rule 603.f. to control and manage weedy, annual vegetation to prevent weed debris and to prevent dispersing seeds onto adjacent lands. Date: 02/02/2018

Response: CA COMPLETED Date of Completion: 01/31/2018

Operator Comment: To comply with Rule 603.f all of the weeds were mowed and removed from around the production equipment. Due to heavily drifted snow, a minimal area could not be mowed. These areas will be addressed when the snow drifts melt off. Bonanza Creek will continue the annual weed treatment around production equipment, but will also add interim reclamation areas to the weed treatment scope of work. Please see the attached pictures to verify the completed corrective actions.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

3 CA# 114141

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 02/16/2018

Response: CA COMPLETED

Date of Completion: 02/02/2018

Operator Comment: To comply with Rule 1002.f all of the accumulated material in the sediment trap was removed and the walls were redefined.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek

Signed: _____

Title: Env. Manager

Date: 2/2/2018 11:25:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401534346	FIR RESOLUTION SUBMITTED
401534365	State Pronghorn V-32 Photos

Total Attach: 2 Files