



## **Plug to Abandon Procedure**

**Well Name: Stites 21-5B**

# SUMMARY

---

**WELL NAME:** Stites 21-5B  
**API #** 05-077-09364-00  
**DESCRIPTION / OBJECTIVE:** MIRU Service rig to Plug to Abandon wellbore.

## **WELL INFORMATION**

**Surface Location:** Section 20, T9S, R94W  
1465' FNL & 953' FEL  
Mesa County, CO

**Perforations** None

**Casing Program** Surface – 8 5/8” 32 lb/ft J-55 at 1532’ (TOC @ Surface)  
Production - 4½” 11.6 lb/ft I-80 at 6562’ (TOC @ 1048’)

**Tubing** None

**Elevation:** GL: 6664’ RKB: 20’ KB

**PROCEDURE:**

|   | <b>P&amp;A Procedure:</b> | All cement to be neat class G @ 15.8 ppg  | #SX |
|---|---------------------------|---|-----|
| 1 | Plug Base<br>Wasatch      | Balance 200 foot cement plug in 4-1/2 @ 3237-3437   | 16  |
| 2 | Plug Surface<br>Shoe      | Balance 100 foot cement plug in 4-1/2 @ 1482-1582   | 8   |
| 3 | Plug Surface              | Shoot 4 holes at 100<br>Balance 100 foot cement plug inside and out 4-1/2 @ 0-100   | 28  |
| 4 | Surface Marker            | Cut off casing 3-4' below GL<br>Install abandonment marker over SHL as per COGCC regulations. The following minimum information shall be permanently placed on the marker with a plate beaded on by welding:<br>Operator name<br>Lease number<br>Well name and number<br>API number<br>Location by ¼ ¼ Section, Township and Range. |     |

## CONTACTS:

### Completions Manager

John Grubich – 970-589-9496 (c)  
970-812-5312 (o)

### Production Manager

Milt Johnson – 970-230-1011

### Production Superintendent

TJ Cordova – 970-250-9519

### Senior Regulatory Manager

Wayne Bankert -970-985-5383

### Completion Consultant

Dan Hacking – 970-778-1063

### COGCC

Curtis Conklin - 970-487-3888

Craig Burger - 970-625-2497