

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401483879
Date Received:
12/12/2017

FIR RESOLUTION FORM

CA Summary:
4 of 4 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Lindsey Rider 970-285-2711 lrider@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102427
Inspection Date: 11/24/2017 FIR Submit Date: 11/27/2017 FIR Status:

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335676

Location Name: NPR Number: K10-596 County:
Qtrqr: NESW Sec: 10 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.627280 Longitude: -108.155610

FACILITY - API Number: 05-045-00 Facility ID: 335676

Facility Name: NPR Number: K10-596
Qtrqr: NESW Sec: 10 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.627280 Longitude: -108.155610

CORRECTIVE ACTIONS:

1 CA# 112074
Corrective Action: Clean up stained Soil around Well Heads. Date: 12/04/2017

Response: CA COMPLETED Date of Completion: 12/04/2017

Operator Comment: Stained soil removed from location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 112075

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details; performing further enlargement/definition of ditch if determined necessary to make it an effective BMP.

Date: 12/01/2017

Response: CA COMPLETED

Date of Completion: 12/04/2017

Operator
Comment: Stormwater controls repaired.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 112076

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 12/01/2017

Response: CA COMPLETED

Date of Completion: 12/04/2017

Operator
Comment: Stormwater controls repaired.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 CA# 112077

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 12/01/2017

Response: CA COMPLETED

Date of Completion: 12/04/2017

Operator
Comment: Stormwater controls repaired.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lindsey Rider

Signed: _____

Title: EHS Lead

Date: 12/12/2017 3:19:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401483879	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files