

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401482156

Date Received:

12/11/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lorne C Prescott</u>	<u>9708125311</u>	<u>lprescott@laramie-energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102472

Inspection Date: 12/07/2017

FIR Submit Date: 12/11/2017

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452807

Location Name: CC Number: 0697-03-07 Pad County: _____

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

FACILITY - API Number: 05-045-00 Facility ID: 452807

Facility Name: CC Number: 0697-03-07 Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

CORRECTIVE ACTIIONS:

1 CA# 113292

Corrective Action: CA: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 12/12/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Inspection document was submitted on 12/11/2017 and has CA date of 12/12/2017. The Corrective Action fails to recognize that the final construction activities are ongoing at this location. The preliminary/pre-construction BMPs that have been installed provide perimeter controls and prevention of sediment runoff, including the areas

in the vicinity of the sediment traps. Implementation of Final BMPs will include adjustments to the existing Preliminary/pre-construction BMPs and the completion of inlet/outlet protection for sediment traps.

COGCC Decision: **Not Approved**

COGCC Representative: At this location, the BMPs should have been installed per good engineering practices at the time of the inspection. Sediment Traps are improperly installed. CA date was attainable; this was not a valid basis for review. BMPs installed prior to & during Construction must be effective and installed with Good Engineering Practices. Some errors in the COGCC data base delayed COGCC response to this FIRR.

COGCC Supervisor: At this location, the BMPs should have been installed per good engineering practices at the time of the inspection. Sediment Traps are improperly installed. CA date was attainable; this was not a valid basis for review. BMPs installed prior to & during Construction must be effective and installed with Good Engineering Practices. Some errors in the COGCC data base delayed COGCC response to this FIRR.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed: _____

Title: Reg & Enviro Compliance

Date: 12/11/2017 2:00:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401482156	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files