



SURFACE CASING CHECK

Well Name LOST #NPP31T3434 HNB

☐ New Drill ☐ Refiling ☐ Deepen ☐ Re-Enter ☐ Recomplete and Operate ☒ Plug and Abandon ☐ Casing Repair

SB5 Base of Fox Hills 116' ± 50' = 166'

Cheyenne Basin Map Base of Fox Hills _____

Fox Hills Protection Area 5% Rule _____

Deepest Water Well w/in One Mile 1040' ± 50' = 1090' -

Operator-Proposed Surface Casing Depth _____

Actual Surface Casing Depth 1120'

Change Permit Surface Casing Depth from _____ to _____

OK on ☐ this well's or ☐ offset well's induction log at _____