

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401544002

Date Received:

02/13/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674901964

Inspection Date: 11/09/2017

FIR Submit Date: 11/14/2017

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333773

Location Name: IGE-N33N8W Number: 16SWSE County: LA PLATA

Qtrqtr: SWSE Sec: 16 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099790 Longitude: -107.719940

FACILITY - API Number: 05-067-00 Facility ID: 295625

Facility Name: IGE Number: 139

Qtrqtr: SWSE Sec: 16 Twp: 33N Range: 8W Meridian: N

Latitude: 37.099790 Longitude: -107.719940

CORRECTIVE ACTIONS:

1 ☒ CA# 110656

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS.

Date: 11/15/2017

Response: CA COMPLETED

Date of Completion: 11/06/2017

Operator
Comment:

Tightened bull plug.

COGCC Decision: Approved pending re-inspection

Date of completion listed by the operator is prior to the date of inspection. Field inspection document #674901964

COGCC Representative: was conducted on 11/9/2017. Catamount representative tightened the bull plug on the load out valve at the request of COGCC EPS.

2 ☒ CA# 110657

Corrective Action: Comply with Rule 603.f.

Date: 12/14/2017

Response: CA COMPLETED

Date of Completion: 11/20/2017

Operator Comment: Removed trailer.

COGCC Decision: Approved pending re-inspection

COGCC Representative: During 12/13/17 follow up field inspection, trailer had been moved to Semler #1 location.

3 ☒ CA# 110658

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS.

Date: 11/15/2017

Response: CA COMPLETED

Date of Completion: 11/06/2017

Operator Comment: tightened bull plug

COGCC Decision: Approved pending re-inspection

COGCC Representative: Inspection document #674901964 was conducted on 11/9/17. Valve on AST was found to be leaking on that date by COGCC staff.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed:

Title: Geo/Eng Tech

Date: 2/13/2018 11:37:11 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401544002	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files