

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401469163

Date Received:

11/28/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

Sabre.Beebe@bp.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601965

Inspection Date: 08/24/2017

FIR Submit Date: 09/05/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326055

Location Name: MORRISON FED GU G-N34N6W Number: 7NESE County: LA PLATA

Qtrqr: NESE Sec: 7 Twp: 34N Range: 6W Meridian: N

Latitude: 37.225639 Longitude: -107.564186

FACILITY - API Number: 05-067-00 Facility ID: 215790

Facility Name: MORRISON FEDERAL B Number: 1

Qtrqr: NESE Sec: 7 Twp: 34N Range: 6W Meridian: N

Latitude: 37.225639 Longitude: -107.564186

CORRECTIVE ACTIONS:

1 ☒ CA# 97770

Corrective Action: Remove debris and materials from the well pad and interim reclamation areas, or provide a surface owner waiver letter that includes a map delineating the areas that the surface owner will use, and interim reclamation areas.

Date: 11/17/2017

Response: CA COMPLETED

Date of Completion: 10/09/2017

Operator Comment: BP has worked with the landowner on this location to remove all the debris that belonged to them. The landowner has moved the pile of rock and concrete off the BP disturbance area. This pile is to be utilized by the landowner in the spring in his irrigation ditches for erosion and silt controls. All the other debris has been

removed from the well pad, but remains near the pad and will be utilized by the landowner in the spring of 2018. Landowner was not willing to move this pile any further than he moved it.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 97771

Corrective Action: Stabilize northern cut-slope. Revegetation will significantly help stabilize this area. Mulching will likely be needed.

Date: 11/01/2017

Response: CA COMPLETED

Date of Completion: 11/27/2017

Operator Comment: The cut slope on this location has been seeded and hydromulched to attempt to germinate vegetation in the spring to control the erosion. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: BP has worked with the landowner on moving the concrete/rock pile off the well pad to the extent the landowner would move it and the other trash items have been removed by the landowner as this stuff belonged to him. The cut slope has been reseeded and hydromulched for re-vegetation to stabilize the cut. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 11/28/2017 9:53:13 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401469163	FIR RESOLUTION SUBMITTED
401469186	CA completion photos

Total Attach: 2 Files