

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401499162
Date Received:
01/02/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		SanJuanCOGCC@bp.com Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602243
Inspection Date: 11/08/2017 FIR Submit Date: 11/17/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326598

Location Name: WOMMER GAS UNIT A- N35N7W Number: 24SESW County: LA PLATA
Qtrqr: SESW Sec: 24 Twp: 35N Range: 7W Meridian: N
Latitude: 37.282409 Longitude: -107.590220

FACILITY - API Number: 05-067- -00 Facility ID: 258655

Facility Name: WOMMER A Number: 2
Qtrqr: SESW Sec: 24 Twp: 35N Range: 7W Meridian: N
Latitude: 37.282409 Longitude: -107.590220

CORRECTIVE ACTIONS:

1 ☒ CA# 111030

Corrective Action: Install stormwater controls to stabilize erosion in the southern portion of the project area. Date: 12/22/2017

Response: CA COMPLETED Date of Completion: 12/20/2017

Operator Comment: Erosion/Storm Water has been addressed on the Wommer A 2 by installing rock run downs in the erosional channels exiting location. Diversion ditches have been re-installed to channel storm water to the rock rundowns to prevent additional channeling in the future. Please see attached photos of all work completed on 12/20/2017

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Erosion/Storm Water has been addressed on the Wommer A 2 by installing rock run downs in the erosional channels exiting location. Diversion ditches have been re-installed to channel storm water to the rock rundowns to prevent additional channeling in the future. Please see attahced photos of all work completed on 12/20/2017

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Construction Specialist

Date: 01/02/2018 7:33:48 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401499162	FIR RESOLUTION SUBMITTED
401499163	Storm water BMP installation photos

Total Attach: 2 Files