

Allison Unit 116T –

Corrective Actions

- Batteries have been removed
- Impacted soil near compressor skid has been cleaned up

API: 05-067-09551

FIR Doc: 685304409



