

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2018

Submitted Date:

03/05/2018

Document Number:

682503173

**FIELD INSPECTION FORM**

Loc ID 312291 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 95620  
Name of Operator: WESTERN OPERATING COMPANY  
Address: 1165 DELAWARE STREET #200  
City: DENVER State: CO Zip: 80204

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		denise.arthur@state.co.us	
		tcrumley@comcast.net	
		steve@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221078	WELL	IJ	01/01/2017	DSPW	075-09204	Propst 1	RI
256304	PIT	AC			-	PROPST 1-A	RI

**General Comment:**

This is a follow-up interim reclamation and stormwater inspection to doc. #675103918, #682502716 and #682502927. Any corrective actions from previous inspections that have not been addressed are still applicable.

**Inspected Facilities**

Facility ID: 221078 Type: WELL API Number: 075-09204 Status: IJ Insp. Status: RI

**Producing Well**

Comment: [PR well, Interim Rec. and Stormwater inspection](#)

Corrective Action:

Date:

Facility ID: 256304 Type: PIT API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? **Fail**  
 Production areas have been stabilized? **Fail** Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment Inspection #675103918 dated 8/25/2017, #682502716 dated 10/18/2017 and #682502927 dated 12/07/2017 required operator to perform remediation/reclamation and stabilize areas downgrade of the produced water pit experiencing substantial and ongoing erosion by 11/15/2017. See Remediation project #10565 for additional information. Erosion degradation on location, and downgrade of the pit have not been stabilized or repaired. No remediation/reclamation activities appear to have been conducted and no stabilization and stormwater BMPs have been installed or maintained per the corrective action. Original corrective action and corrective action date remains applicable.

Corrective Action Perform remediation/reclamation and implement/maintain stabilization BMPs until 910-1 standards are met, at which point revegetation/reclamation activities shall be conducted in accordance to COGCC reclamation standards; Re-grade disturbed areas and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until reclamation has passed. Remediation activities shall be conducted no later than 11/15/2017.

Date 11/15/2017

Overall Interim Reclamation **Fail**

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #675103918 dated 8/25/2017, #682502716 dated 10/18/2017 and #682502927 dated 12/07/2017 required operator to implement temporary stabilization and stormwater controls to prevent further degradation from occurring until more permanent stabilization controls have been implemented and reclamation activities have been conducted. Erosion degradation throughout the location has not been repaired and no BMPs have been implemented and/or maintained. Original CA and CA date remains in place and applicable. This is the fourth inspection requiring stormwater management.

Corrective Action: Properly select, install and maintain stormwater and sediment control BMPs in accordance to 1002.f and good engineering practices.

Date: 10/12/2017

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	256304	846026	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682503174	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393699">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393699</a>