

# Southern Ute 33-9 #17-2

Corrective Actions Taken on the Southern Ute 33-9 #17-2 INC.



Russian thistle debris has been removed and properly disposed of. Storm water management erosion control erosion channels have been established and stabilized in order to prevent future erosion off location.













Location has been reclaimed and seeded to stabilize erosion. Sedimentation was removed and reused for Storm water management erosion control. Erosion channels have been established and stabilized in order to prevent future erosion onto location.









All rig anchors have been properly marked.



Corrective action taken for Photo 8 & 9  
from report.



Corrective action taken for Photo 5  
from report.