

# Florida River Estates 33-9 # 17-3

Corrective Actions Taken on the Florida River Estates 33-9 # 17-3 INC.

Erosion channel has been stabilized in order to prevent future erosion.



Wattles on the Southside of the well pad access entrance were replaced in order to prevent any future erosion.





Storm water management erosion control channel East of production tanks has been stabilized in order to prevent future erosion on location. Wattles on the East of the well pad near production tanks were replaced in order to prevent any future erosion.

