

BNS SERVICES, LLC

244 BURTARD LN
PARACHUTE, CO 81635
NATE SCHAEFFER (970)-986-0513
BNSSERVICES@SOPRIS.NET

14151

To URSA Date 2-22-18
Address North Bank E Phase #1 Purchase Order No. _____
Location DAVE / KIP

Description of Work	Hours
Plug And Abandon Conductor And mouse Holes	
P+A the E-8	
P+A 2 mouse Holes	
unable to Find the E-13 And E-7 Conductors	
Cut Conductor to 4 feet Below ground level	
Fill with gravel And concrete	
weld Cap on Conductor	
Haul of Conductor parts And mouse Hole pipe	
E-8 API 05-045-15808	

No.	Equipment & Material	Hours	Rate	Amount	Labor	Hours	Rate	Amount
	Pickup	2			Foreman	3		
	Trailer	2			Labor N	9		
	10 SD mini Ex	9			Labor			
	welder (Devon)	5			Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Total			
					Labor			
					Total			
					Equip.			

Total Equipment

Total

Purchaser [Signature] Date _____ By _____

BNS SERVICES, LLC

244 BURTARD LN
PARACHUTE, CO 81635
NATE SCHAEFFER (970)-986-0513
BNSSERVICES@SOPRIS.NET

14150

To URSA Date 2-21-18
Address North Bank E Phase #1 Purchase Order No. _____
Location DAVE / KIP

Description of Work	Hours
Plug And Abandon Conductor And mouse Holes	
P+A the E-6, E-9 And E-18	
P+A 3 mouse Holes	
Cut Conductors to 4 feet below ground Grade	
Fill with gravel And concrete	
weld Cap on Conductor	
E-6 API 05-045-15805	
E-9 API 05-045-15807	
E-18 API 05-045-16046	

No.	Equipment & Material	Hours	Rate	Amount	Labor	Hours	Rate	Amount
	Pickup	9			Foreman	4		
	Trailer	1			Labor N	9		
	D-10 SD mini Ex	1			Labor			
	welder (Devon)	6			Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Total			
					Labor			
					Total			
					Equip.			

Total Equipment

Total

Purchaser [Signature] Date _____ By _____