

# BNS SERVICES, LLC

244 BURTARD LN  
PARACHUTE, CO 81635  
NATE SCHAEFFER (970)-986-0513  
BNSSERVICES@SOPRIS.NET

# 14162

To UKSA Date 3-1-18  
Address Gypsum Ranch B Phase #1 Purchase Order No. \_\_\_\_\_  
Location Dave/Kip

Description of Work	Hours
Plug And Abandon Conductors At the Gypsum Ranch B	
P+A the B-5 and B-11	
P+A 2 mouse holes	
Cut Conductors to 4 feet below ground grade	
Fill with gravel and concrete	
weld cap on conductors	
B-5 API # 05-045-16037	
B-11 API # 05-045-16042	

No.	Equipment & Material	Hours	Rate	Amount	Labor	Hours	Rate	Amount
	Pickup	1			Foreman			
	Trailer	1			Labor N	4		
	JD 50 mini ex	4			Labor			
	Welder Devon	4			Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Total			
					Labor			
					Total			
					Equip.			

Total Equipment \_\_\_\_\_ Total \_\_\_\_\_

Purchaser Dave 3-9-18 Date \_\_\_\_\_ By \_\_\_\_\_

# BNS SERVICES, LLC

244 BURTARD LN  
PARACHUTE, CO 81635  
NATE SCHAEFFER (970)-986-0513  
BNSSERVICES@SOPRIS.NET

# 14163

To UKSA Date 3-2-18  
Address Conductor P+A Phase #1 Purchase Order No. \_\_\_\_\_  
Location Dave/Kip

Description of Work	Hours
Load And Haul off (conductor pieces) From the	
Snyder A, River Ranch C, Hanks B, Island Park B, and Gypsum	
Ranch B	
Clean up And Spread gravel on the River Ranch C and	
Gypsum Park B	

No.	Equipment & Material	Hours	Rate	Amount	Labor	Hours	Rate	Amount
	Pickup	3			Foreman			
	Trailer	3			Labor N	7		
	JD 50 mini ex	1			Labor			
	Case 450 skid	4			Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Total			
					Labor			
					Total			
					Equip.			

Total Equipment \_\_\_\_\_ Total \_\_\_\_\_

Purchaser Dave 3-9-18 Date \_\_\_\_\_ By \_\_\_\_\_