

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Battery sign at entrance.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Drilling chemicals being stored on location.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Drilling chemicals being stored on location.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Drilling chemicals being stored on location.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Spilled material around pallet.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Spilled material, pallet debris, unneeded equipment.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Spilled material, pallet debris, unneeded equipment.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Spilled material, pallet debris, unneeded equipment.

O10A 596 Pad
N. Parachute WF04B O10A 596
Api. Number: 05-045-12353
Inspection Number: 689701146



Spilled material, pallet debris, unneeded equipment.