



Well Summary Report

(Callon) Scritsmier #1-26 3/10/2018 06:00 - 3/11/2018 06:00

API 05-123-11704	State/Province Colorado	County Weld	Field Name Non-Operated	Well Status	Total Depth (ftKB)	Primary Job Type Abandon Well
---------------------	----------------------------	----------------	----------------------------	-------------	--------------------	----------------------------------

Time Log						
Start Time	Dur (hr)	End Time	Code	Category	Com	
06:00	2.00	08:00	inactive	inactive		
08:00	2.00	10:00	GOP	General Operations	Level road into field, Dig WH, Verify CSG size of 9 5/8"	
10:00	20.00	06:00	inactive	inactive		

(Callon) Scritsmier #1-26 3/12/2018 06:00 - 3/13/2018 06:00

API 05-123-11704	State/Province Colorado	County Weld	Field Name Non-Operated	Well Status	Total Depth (ftKB)	Primary Job Type Abandon Well
---------------------	----------------------------	----------------	----------------------------	-------------	--------------------	----------------------------------

Time Log						
Start Time	Dur (hr)	End Time	Code	Category	Com	
06:00	8.00	14:00	inactive	inactive		
14:00	2.00	16:00	IWHD	Install Wellhead	Prep 9 5/8" CSG Top, weld on 9 5/8" by 11" 5K flange, NU 11" 5K by 7" 5K spool, install cellar ring, backfill hole.	
16:00	3.00	19:00	SRIG	Rig Up/Down	MIRU Ensign Rig #312 & Equipment	
19:00	1.00	20:00	CTRL	Crew Travel		
20:00	10.00	06:00	inactive	inactive		

(Callon) Scritsmier #1-26 3/13/2018 06:00 - 3/14/2018 06:00

API 05-123-11704	State/Province Colorado	County Weld	Field Name Non-Operated	Well Status	Total Depth (ftKB)	Primary Job Type Abandon Well
---------------------	----------------------------	----------------	----------------------------	-------------	--------------------	----------------------------------

Time Log						
Start Time	Dur (hr)	End Time	Code	Category	Com	
06:00	1.00	07:00	CTRL	Crew Travel		
07:00	2.50	09:30	SRIG	Rig Up/Down	Torque 11" WH flange bolts, NU spacer 7" spool & BOPs, MU Tricone BHA	
09:30	3.00	12:30	RUTB	Run Tubing	RIH w/ 6 1/8" Tricon bit to 415', circulate hole clean,	
12:30	0.75	13:15	TRIP	Tripping	TOOH, LD drill collars & BHA	
13:15	2.75	16:00	SRIG	Rig Up/Down	MU Mule shoe BHA, stand by for cementers	
					Cement Crew got stuck on other job, Secure WH, SDFN, plan on cementing in AM	
16:00	1.00	17:00	CTRL	Crew Travel		
17:00	13.00	06:00	inactive	inactive		

(Callon) Scritsmier #1-26 3/14/2018 06:00 - 3/15/2018 06:00

API 05-123-11704	State/Province Colorado	County Weld	Field Name Non-Operated	Well Status	Total Depth (ftKB)	Primary Job Type Abandon Well
---------------------	----------------------------	----------------	----------------------------	-------------	--------------------	----------------------------------

Time Log						
Start Time	Dur (hr)	End Time	Code	Category	Com	
06:00	1.00	07:00	CTRL	Crew Travel	Safety Meeting, fire up equip	
07:00	0.25	07:15	TRIP	Tripping	RIH w/ mule shoe & 2 3/8" TBG to 400'	
07:15	0.75	08:00	SRIG	Rig Up/Down	RU Ranger Cement equip. hold safety meeting	
08:00	0.50	08:30	CEMT	Surface plug	Pump Surface plug: pump 5bbls fresh, establish circulation, pum 244sks, 1.15 yield, glass G cement, 15.8ppg, 50bbls slurry, saw returns to surface after 48bbls	
08:30	0.25	08:45	PULT	Pull Tubing	POOH LD TBG	
08:45	1.25	10:00	SRIG	Rig Up/Down	Top wellbore off with cement, RDMO Ranger Cement Equip, RDMO Ensign Rig #312 & Equip	
10:00	20.00	06:00	inactive	inactive		

(Callon) Scritsmier #1-26 3/15/2018 06:00 - 3/16/2018 06:00

API 05-123-11704	State/Province Colorado	County Weld	Field Name Non-Operated	Well Status	Total Depth (ftKB)	Primary Job Type Abandon Well
---------------------	----------------------------	----------------	----------------------------	-------------	--------------------	----------------------------------

Time Log						
Start Time	Dur (hr)	End Time	Code	Category	Com	
06:00	8.00	14:00	inactive	inactive		
14:00	1.00	15:00	GOP	General Operations	Dig up & remove cellar, cut WH off 5' below ground level, install dry hole marker, backfill hole	
15:00	15.00	06:00	inactive	inactive		