

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/12/2018

Submitted Date:

03/23/2018

Document Number:

688400041**FIELD INSPECTION FORM**Loc ID 440806 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452083	WELL	DG	09/14/2017		123-45388	Marcus LD 11-380HNX	WO

**General Comment:**

**Inspected Facilities**

Facility ID: 452083 Type: WELL API Number: 123-45388 Status: DG Insp. Status: WO

**Complaint**

Comment:

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 2-20-2018

Complaint Contacted:

Date: 2-23-2018 Time 1330 Hrs

Location #: 440806

Inspection Document #: 688400041

Nature of complaint: Noise

Field Inspector Actions:

On 2-12-2018, I was contacted by complaint specialist Megan Adamczyk in reference to some complaints received by the COGCC in reference to noise complaint. The complaint stated the issues were occurring in the Brighton area originating from the Great Western, Marcus location.

On 2-12-2018, I attempted to make contact with the complaint he indicated in the complaint he was experiencing noise coming from the Great Western Marcus location. I performed a complete site inspection of the Marcus location. I reviewed location records, which did not show any abnormal fracking conditions at the time of the complaints. I reviewed third party sound records at the times of the complaint and at no time did the drilling operation exceed COGCC rules according to the sound study information reviewed. During my inspection of the location I observed GW had added additional sound walls from the previous inspections in an attempt to mitigate noise on location. At the time of the inspection all lighting appeared to be pointed down and toward the ground per COGCC rules.

No violation of COGCC rules were observed at the time of the inspection of the track operation nor in the surrounding neighborhood.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

**Well Stimulation**

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

**Observation:**

Other: \_\_\_\_\_

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401587468	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414465">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414465</a>
688400042	Sound study results	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414458">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4414458</a>