

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2018

Submitted Date:

04/06/2018

Document Number:

691300093

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Kraich, Adam On-Site Inspection
 418750 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10544
 Name of Operator: HIGHPOINT ENERGY LLC
 Address: 361 71ST AVE
 City: GREELEY State: CO Zip: 80634

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Precup, Jim		james.precup@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
,		mnotter@rocheconstructors.com	
,		bill@blackrockoil.com	
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418740	WELL	PR	11/01/2017	OW	123-31988	RBF 15B	PR

General Comment:

Inspected Facilities

Facility ID: 418740 Type: WELL API Number: 123-31988 Status: PR Insp. Status: PR

Complaint

Comment:

Field Inspector Assigned: Adam Kraich
 Complaint Received:
 Date: 4-5-2018
 Complaint Contacted:
 Date: 4-5-2018 Time: 15:32
 Location #: 418750
 Inspection Document #: 691300093
 Nature of complaint: Noise
 Field Inspector Actions:
 On 4-5-2018, I was contacted by COGCC staff in reference to a complaint received by via website in reference to a vibration complaint. The complaint stated he thought the issues were coming from the Highpoint RBF location located on the northeast corner of HWY 392, & HWY 287.
 On 4-5-2018, I attempted to make contact with the complainant via phone, no answer, and left message.
 I performed a complete site inspection of the Highpoint RBF location. After speaking with Highpoint staff on location, there was no obvious or upset condition within the last 48 hours. There is a large combustor on location burning tank VOC, however the combustor was producing no sound at all at time of inspection, and per Highpoint staff on location, it is normal for its operation.
 The complainant's residence is 504' away from the RBF location, more specifically the locations combustor. I did not perform a sound study due to the residence being located on a collector road, which had moderate traffic at time of inspection.
 No noise violation of COGCC rules were observed at the time of the inspection of the production operations, nor in the surrounding neighborhood. However, after further investigation of the site, and meeting with the operator, It was determined that the location is utilizing a flare to produce in place of an available sales line.
 The only well currently running on location is the RBF 15B (123-31988). This well, along with remaining wells on the pad were recently fracked into by separate operators.
 Speaking with COGCC engineering staff, it has been determined that the operator must submit a sundry notice for permission to flare. Highpoint officials, specifically Bill Fisher, (970-539-0206, bill@blackrockoil.com) is aware of the requirement and will submit all necessary documentation to COGCC engineering for approval.
 All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date: