

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2018

Submitted Date:

04/10/2018

Document Number:

691300094**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 321259      Kraich, Adam      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 39560Name of Operator: TOP OPERATING COMPANYAddress: 3609 S WADSWORTH BLVD STE 340City: LAKEWOOD      State: CO      Zip: 80235**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Herring, Debora		toporting@aol.com	
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
HERRING, PAUL	(303) 727-9915	paul.herring@topoperating.com	
HERRING, MURRAY J	(303) 727-9915 x203	murray.herring@topoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206541	WELL	PR	09/01/2017	GW	013-06036	TANAKA BROS 1	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Verified 4/10/2018

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:		Shares berms with steel produced water tankl, and production tank.				
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:		Shares berms with produced water tanks				
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 206541 Type: WELL API Number: 013-06036 Status: PR Insp. Status: PR

**Complaint**

Comment: [Inspection in response to complaint.](#)

[Field Inspector Assigned: Adam Kraich](#)

[Complaint Received:](#)

[Date: 4-6-2018](#)

[Complaint Contacted:](#)

[Date: 4-10-2018 Time 09:57 AM](#)

[Location #: 321259](#)

[Inspection Document #: 691300094](#)

[Nature of complaint: Noise](#)

[Field Inspector Actions:](#)

[On 4-10-2018, I was contacted by complaint specialist Megan Adamczyk in reference to a complaint received by the COGCC in reference to noise. The complainant stated the issues were coming from the Tanaka 1 production facility \(location ID 321259\).](#)

[Complaint: It sounds like the pressure release valves are going off- it shoots gas with a brownish and sometimes blackish color into the air. There are two different valves that shoot it out. One is on a big holding tank and the other is on a brown vertical looking device. It is pretty noisy when it happens. One day a worker was down there working on it, so I went to ask him about it. He told me the old wells were starting to do that because of the fracking wells in the area were building up pressure. Since I talked to him I haven't noticed it again.](#)

[On 4-10-2018, I made contact with the operator, Rod Herring at approximately 9:44am, who informed me the well is hard shut in at the master valve due to a downhole issue. I informed him of the nature of the complaint. He stated there would be no reason the issue that he is aware of.](#)

[There was no evidence of a high pressure event, as rain caps were still present on the pressure relief valves on separation equipment, and tanks had no evidence of release.](#)

[On 4-10-2018, I made contact with the complainant, at approximately 9:57am. She stated she had not had an issue since she talked to the operator prior. I informed her of the wells current shut in state, and suggested COGCC notification of issues return if, and when the well returns to production.](#)

[No violation of COGCC rules were observed at the time of the inspection.](#)

[All information reviewed and site inspection information were submitted to the complaint specialist for further review.](#)

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Complaint response</a>	kraicha	04/10/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300095	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4429651">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4429651</a>