

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2018

Submitted Date:

04/18/2018

Document Number:

680303159**FIELD INSPECTION FORM**
 Loc ID 312202 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2116 EAST HIGHWAY 402City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pivonka, Todd		pivonka2010@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219441	WELL	IJ	02/01/2017	ERIW	075-06348	NORTH MINTO J SAND UNIT 1	IJ

General Comment:

P&A Day (3) Weather conditions: High winds continue to create scheduling delays, appropriate safety considerations dictate schedule.

Location**Lease Road:**

Type	Access		
comment:	Maintain lease road until reclamation process requires removal.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 0		corrective date
Comment:	Remove all equipment upon completion of P&A and begin reclamation process.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 219441 Type: WELL API Number: 075-06348 Status: IJ Insp. Status: IJ**Cement**Cement ContractorContractor Name: Timka ResourcesContractor Phone: 970-667-9861Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 4770'Cement Volume (sx): 2

Good Return During Job: _____

Cement Type: _____

Comment: Wireline cut casing @ 2958', pulled/retrieved casing. Windy conditions continue to cause delays in process for safety considerations.Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Continue BMP's for stormwater management until final reclamation is approved.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
P&A Day (3) Work proceeded cutting casing and retrieval. Weather conditions continue to dictate schedule.	schureky	04/18/2018