



Fwd: REM 5151, API 081-06553, Spill ID 2608147

1 message

Fischer - DNR, Alex <alex.fischer@state.co.us>
To: OGCC EnviroScan - DNR <dnr_ogcc.enviroscan@state.co.us>
Cc: Kris Neidel - DNR <kris.neidel@state.co.us>

Tue, Apr 17, 2018 at 1:55 PM

Please upload the attached files as follows:

Document Name(s)	1. April 17, 2018 COGCC email	
Document Number	<i>(leave blank if not already assigned)</i>	
Date Received	4/17/2018	
Is data entry needed?		
Indexing Information	Unique ID Type	Unique ID Number
First	REM	5151
Second		
Third*		
Additional Instructions	Upload email to REM 5151	

----- Forwarded message -----

From: **Fischer - DNR, Alex** <alex.fischer@state.co.us>
Date: Tue, Apr 17, 2018 at 1:52 PM
Subject: REM 5151, API 081-06553, Spill ID 2608147
To: Dave Weinert <davew@kirkwoodcompanies.com>, Gene Vandeeest <genev@kirkwoodcompanies.com>, Scott Kerr <scottk@kirkwoodcompanies.com>
Cc: Kris Neidel - DNR <kris.neidel@state.co.us>

Dave-

In reviewing stale projects, we came across the following:

Maudlin Gulch Federal Unit 26 081-06553
Spill ID: 2608147
REM: 5151

The last document we received was a report from WESCO, "December 23, 2011 Maudlin Gulch Federal Unit 26 Flowline Spill Follow-Up Soil Sampling Report." (Document Number 2330223) There were exceedances to Table 910-1, mainly TPH, where WESCO was going to do additional work and sampling.

Action Item:

WESCO to provide current status of this REM.

WESCO to provide documentation that the spill as been remediation to Table 910-1, and then request closure. Please provide this information on an eForm 27.

Thanks
Alex

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc