

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2018

Submitted Date:

04/20/2018

Document Number:

690900015**FIELD INSPECTION FORM**Loc ID 324754 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Harwell, Clay	405-429-6630	sandridgeenvironmental@san dridgeenergy.com	
Waldron, Emily		emily.waldron@state.co.us	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296567	WELL	PR	02/13/2015	OW	057-06469	SPICER 3-32H	EI

General Comment:

On April 18, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Spicer 3-32H Location (Location ID: 324754) API 057-06469. Weather was sunny and temperatures about 25 degrees Fahrenheit.

The following is a summary:

- Oil staining on the ground beneath the catchment containment at the load out area.
- Oil staining on the gravel in secondary containment near Tank # 9007.
- Entrance sign on the ground.

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	• Entrance sign on the ground.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	06/29/2018

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			
Crude Oil	Truck Loadout	<= 1 bbl			
Comment:	<ul style="list-style-type: none"> • Oil staining on the ground beneath the catchment containment at the load out area. • Oil staining on the gravel in secondary containment near Tank # 9007. 				
Corrective Action:	Remediate the oily stains and salty stains beneath catchment containments, valves, fittings, and unions at well head and pump jack. 906.a, Spills/Releases, Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff., Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.			Date:	05/20/2018

In Containment: No

Comment: ☒ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:			
	Date:		

Flaring:

Type			
Comment:			
Corrective Action:			
	Date:		

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: • Oil staining on the ground beneath the catchment containment at the load out area. • Oil staining on the gravel in secondary containment near Tank # 9007.

Corrective Action: Remediate the oily stains and salty stains beneath catchment containments, valves, fittings, and unions at well head and pump jack. 906.a, Spills/Releases, Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff., Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil. Train and educate staff and contract personnel on house keeping with zero spills within the load out areas, and that staining beneath valves, fittings, unions, etc. may be a result of leaking/loose/weeping valves, fitting, unions, etc. that should immediately be addressed.

Date: 05/20/2018

Reportable: NO

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<p>On April 18, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Spicer 3-32H Location (Location ID: 324754) API 057-06469. Weather was sunny and temperatures about 25 degrees Fahrenheit.</p> <p>The following is a summary:</p> <ul style="list-style-type: none"> • Oil staining on the ground beneath the catchment containment at the load out area. • Oil staining on the gravel in secondary containment near Tank # 9007. • Entrance sign on the ground. <p>Corrective Actions (CAs):</p> <ul style="list-style-type: none"> • By May 20, 2018, remediate the oily stains and salty stains beneath catchment containments, valves, fittings, and unions at well head and pump jack. <p>906.a, Spills/Releases, Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff., Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.</p> <p>Train and educate staff and contract personnel on house keeping with zero spills within the load out areas, and that staining beneath valves, fittings, unions, etc. may be a result of leaking/loose/weeping valves, fitting, unions, etc. that should immediately be addressed.</p>	fischera	04/20/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900016	20180418 SandRidge Inspection Spicer Location ID 324754	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4440469
690900017	INSP Photo Spicer 3-32H Location 324754 20180418	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4440470