

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401615586  
Date Received:  
04/20/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fitzgerald, Edie</u>		<u>ediefitzgerald@tcenergy.us</u>
<u>Amato, Joe</u>		<u>josephamato@tcenergy.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102764  
Inspection Date: 03/08/2018 FIR Submit Date: 03/23/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307462

Location Name: GOLDEN EAGLE MINE-633S67W Number: 20NWSW County: LAS ANIMAS  
Qtrqtr: NWS Sec: 20 Twp: 33S Range: 67W Meridian: 6  
W  
Latitude: 37.157167 Longitude: -104.917478

FACILITY - API Number: 05-071-00 Facility ID: 217696

Facility Name: GOLDEN EAGLE MINE Number: GE-40-89  
Qtrqtr: NWS Sec: 20 Twp: 33S Range: 67W Meridian: 6  
W  
Latitude: 37.157167 Longitude: -104.917478

CORRECTIVE ACTIIONS:

1 CA# 115195

Corrective Action: Evaluate and assess progress of vegetation at site; reseeding (& other Reclamation activities/inputs ) as needed, indicated by site assessment. Continue to monitor and manage site until Final Reclamation passes. Date: 05/23/2018

Response: CA COMPLETED Date of Completion: 04/19/2018

The location was re-seeded. See attachment for details.

Operator  
Comment:

COGCC Decision:

COGCC  
Representative:

2 CA# 115196

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 04/30/2018

Response: CA COMPLETED

Date of Completion: 04/19/2018

Operator  
Comment:

The dirt berm diversion on the west side of location was dominated to direct run on away from the project. See attachment for details.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The dirt berm diversion on the west side of location was dominated to re-direct stormwater run on. The location was re-seeded. See attachment for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: SR Environmental Tech.

Date: 4/20/2018 2:12:59 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401615599	Erosion repair and re-seeded location
-----------	---------------------------------------

Total Attach: 1 Files